

# Index

Page numbers preceded by PDF: indicate topics found online in downloadable PDF format at [www.prenhallprofessional.com/title/0132300214](http://www.prenhallprofessional.com/title/0132300214)

## A

- acceptance charts, 682
- accountable (RACI matrix), 555
- accuracy, precision versus, 413-415
- action and effect diagrams (AED). *See* reverse fishbone diagrams
- actions, taking (levels of engagement), PDF:883
- Activate phase (IDEA), 73, 80
- activity charts. *See* Activity Network Diagram (AND); Gantt charts
- activity flowcharts. *See* process maps
- activity lists. *See* Gantt charts; PERT charts
- Activity Network Diagram (AND), 127-135.  
*See also* Gantt charts; PERT charts; process maps; QFD (quality function deployment); 7M toolset; WBS (work breakdown structure)
- Activity on Node (AON). *See* Activity Network Diagram (AND)
- Activity-on-Arrow (AOA). *See* Activity Network Diagram (AND)
- Adapt phase (LMAD), 97, 107-109
- adaptive nature of methods, 3
- additive law of probability, 695
- adjustment factors (DMAIC), 16
- ADM (Arrow Diagramming Method).  
*See* Activity Network Diagram (AND)
- adult learning theory, PDF:831-PDF:832
- advanced product planning, PDF:857-PDF:858, PDF:891-PDF:894
- advertising
  - AIDA model, PDF:831
  - goals, discovery-based learning and, PDF:830-PDF:831
- AED (action and effect diagrams). *See* reverse fishbone diagrams
- affinity charts. *See* affinity diagrams
- affinity diagrams, 136-142. *See also* benchmarking; brainstorming; DOE (design of experiment); interrelationship diagrams; KJ analysis; 7M toolset; voice of customer gathering techniques
- AIDA model (discovery-based learning), PDF:831
- alternative hypothesis, in hypothesis testing, 339
- analysis of means (ANOM). *See* ANOVA (analysis of variance)
- analysis of variance. *See* ANOVA (analysis of variance)
- analytical criteria method. *See* prioritization matrices
- analytical tree. *See* tree diagrams
- Analyze phase
  - DMADV, 50
  - DMAIC, 15, 21-22
  - UAPL, 82, 90-91
- AND (Activity Network Diagram), 127-135.  
*See also* Gantt charts; PERT charts; process maps; QFD (quality function deployment); 7M toolset; WBS (work breakdown structure)
- andragogy, PDF:832
- ANOM (analysis of means). *See* ANOVA (analysis of variance)
- ANOVA (analysis of variance), 142-159. *See also* cause-and-effect prioritization matrix; hypothesis testing
- AOA (Activity-on-Arrow). *See* Activity Network Diagram (AND)
- AON (Activity on Node). *See* Activity Network Diagram (AND)
- appreciating interdependence (levels of engagement), PDF:882
- area charts, 331. *See also* histograms
- Arrow Diagramming Method (ADM). *See* Activity Network Diagram (AND)
- association techniques for probing questions, 742
- attribute control charts, 231-232
- attribute measurement system analysis in market research, 747
- attribute MSA, 419, 425-429

## B

- backward fishbone diagrams. *See* reverse fishbone diagrams
- bar charts, 324, 331, 334. *See also* histograms

- benchmarking, 160-164, PDF:789-PDF:791.  
*See also* MPQP; Pugh concept evaluation; QFD (quality function deployment); RWW analysis; solution selection matrix; voice of customer gathering techniques
- elements of, PDF:792
  - history of, PDF:791
  - leading practices, examples of, PDF:793-PDF:795
  - partners, selecting, PDF:793
  - performance indices and, PDF:792-PDF:793
  - tips for, PDF:795, PDF:797
- benefit cost analysis. *See* cost/benefit analysis
- Berry's ten characteristics of quality, 391
- best practices
  - project management, PDF:803
  - sharing, PDF:800
- best-fit lines in regression analysis, 595
- binary logistic regression, 595
- binomial distribution (statistics), 690
- Black Belts, PDF:816
- board of governors, PDF:822
  - phase-gate reviews, PDF:823
  - project selection, PDF:822-PDF:823
- box-and-whisker plots. *See* boxplots
- Box-Cox transformations, 228-229
- boxplots, 164-168, 324, 327. *See also* control charts; dotplots; graphical methods; histograms; statistical tools
- brainstorming, 168-172. *See also* Activity Network Diagram (AND); affinity techniques; ANOVA (analysis of variance); benchmarking; cause-and-effect diagrams; control charts; DOE (design of experiment); fault tree analysis; 5-Whys; FMEA; Gantt charts; GOSPA; hypothesis testing; interrelationship diagrams; KJ analysis; MSA; PDPC; PERT charts; process maps; Pugh concept evaluation; QFD (quality function deployment); RACI matrix; risk mitigation plans; solution selection matrix; SWOT; TRIZ; value stream analysis; voice of customer gathering techniques
- business case analysis. *See* RWW analysis
- business goals of IDEA, 74-75
- business planning process, benchmarking in, PDF:790
- business questions
  - answered by DMAIC, 16-17
  - answered by Lean methodology, 31
  - in LMAD, 100-101
  - UAPL, 84
- C**
- c-charts, 234-235. *See also* control charts
- C-shape matrix, 403
- C and E diagrams. *See* cause-and-effect diagrams
- C and E matrix. *See* cause-and-effect prioritization matrix
- capability analysis. *See* process capability analysis
- career paths for Six Sigma and project management integration, PDF:815-PDF:818
- causation in regression analysis, 595
- cause and prevention diagrams, 185, 198-203.  
*See also* cause-and-effect diagrams; risk mitigation plans
- cause enumeration diagrams, 185. *See also* cause-and-effect diagrams
- cause-and-effect analyses of performance variations, PDF:779-PDF:780
- Cause-and-Effect Diagram and Cards (CEDAC), 185-186. *See also* cause-and-effect diagrams
- cause-and-effect diagrams, 173-188, 197, 316
- cause-and-effect diagrams. *See also* Activity Network Diagram (AND); affinity diagrams; affinity techniques; ANOVA (analysis of variance); benchmarking; boxplots; brainstorming; cause and prevention diagrams; cause-and-effect prioritization matrix; conjoint analysis; control charts; DOE (design of experiment); dotplots; fault tree analysis; 5-Whys; FMEA; graphical methods; hypothesis testing; interrelationship diagrams; KJ analysis; MPQP; MSA; multi-vari charts; Pareto charts; PERT charts; Porter's 5 Forces; process maps; regression analysis; risk mitigation plans; run charts; scatter diagrams; 7QC toolset; solution selection matrix; value stream analysis; voice of customer gathering techniques
- cause-and-effect matrix. *See* cause-and-effect prioritization matrix
- cause-and-effect prioritization matrix, 184, 188-197. *See also* cause-and-effect diagrams; matrix diagrams, 400
- CDOV (Concept-Design-Optimize-Verify) method, 5-6, PDF:889. *See also* DFSS described, 53-54
- DMADV versus, 55-56
- DMAIC versus, 46-47
- Fast Track project support, PDF:836, PDF:839
  - Concept phase, PDF:839-PDF:842, PDF:847
  - Design phase, PDF:842-PDF:843, PDF:847
  - Optimize phase, PDF:843-PDF:845, PDF:847
  - Verify phase, PDF:845-PDF:848
- objective of, 52
- prerequisites, 56-57
- process flow, 55
- steps in, 54-55
- tools-tasks-deliverables
  - for Concept phase, 59-60
  - for Define phase, 60-61
  - for Optimize phase, 62-63
  - for Verify phase, 63-64
- UAPL versus, 82
- CEDAC (Cause-and-Effect Diagram and Cards), 185-186. *See also* cause-and-effect diagrams; risk mitigation plans
- Central Limit Theorem, 229, 619, 692-693
- central tendency (in descriptive statistics), 684-685
- certainty, defined, 603
- certification levels for Six Sigma and project management integration, PDF:824-PDF:825
- change control logs, PDF:809
- change management plan for SSFM, 73
- change management processes, PDF:809
- charts. *See* matrix diagrams
- check sheets. *See* checklists
- checklists, 204-207. *See also* cause and prevention matrix; data collection matrix; matrix diagrams; 7QC toolset
- in market research, 743
- scorecards versus, 654-655
- chi-square distribution critical values (table), 941

- Chi-square test, example of, 360-367. *See also* hypothesis testing
- closed-ended questions, in market research, 742-746
- coachable and coaching (levels of engagement), PDF:883-PDF:885
- coefficient of determination, in regression analysis, 595
- collaboration  
 achieving with Six Sigma, project management, and communities of practice, PDF:805-PDF:806  
 as level of engagement, PDF:883
- Combination I.D./Matrix method, 472-473, 482-485. *See also* prioritization matrices
- commercialization process, in CDOV method, 52
- commercialization projects. *See* Fast Track projects
- common cause variation (statistics), 686
- communication management, in project management, PDF:811-PDF:812
- communication plans, 405-406. *See also* cause and prevention matrix; control charts; DOE (design of experiment); matrix diagrams; RWW analysis; SMART
- communications management checklist and matrix, PDF:811
- communities of practice, PDF:799-PDF:801  
 Six Sigma and project management integration, PDF:804-PDF:807  
 certification levels, PDF:824-PDF:825  
 governance process, PDF:822-PDF:824  
 human resources, PDF:814-PDF:818, PDF:820  
 organizational structure, PDF:820-PDF:822  
 resource guidance, PDF:824  
 selecting methodology, PDF:807-PDF:814
- Community Relations department  
 (benchmarking leading practice), PDF:794
- comparative scales in market research, 744
- comparative statistics. *See* inferential statistics
- competition, evaluating, PDF:861-PDF:862
- competitive advantage  
 gaining with Six Sigma, project management, and communities of practice, PDF:805  
 SWOT analysis, 702-703
- competitive benchmarking. *See* benchmarking; RWW analysis
- Competitive Position Matrix, 394-395
- completion techniques for probing questions, 742
- complexity of Six Sigma, PDF:827-PDF:828
- Component Deployment QFD matrix, 545
- comprehensive risk rating tools, PDF:811
- concept generation methods. *See* control charts; CTQ (critical-to-quality); interrelationship diagrams; process capability analysis
- Concept phase (CDOV), 54  
 Fast Track project support  
 minimum requirements, PDF:841-PDF:842, PDF:847  
 risk characteristics, PDF:839-PDF:841  
 tools-tasks-deliverables, 59-60
- concept strategy inputs (UAPL), 83
- confidence interval  
 in hypothesis testing, 339  
 in regression analysis, 596  
 in sampling, 619
- confidence level, in hypothesis testing, 341
- conjoint analysis, 207-217. *See also* benchmarking; DOE (design of experiment)
- connections in workplace. *See* relationships in workplace
- Consensus Criteria method, 472, 480-482. *See also* prioritization matrices
- construction techniques for probing questions, 742
- consulted (RACI matrix), 555
- control charts, 217-238. *See also* FMEA; matrix diagrams; process capability analysis; run charts; 7QC toolset; statistical tools
- control limits, recalculating, 225-227
- control plans, 406-407. *See also* ANOVA (analysis of variance); benchmarking; cause and prevention matrix; cause-and-effect prioritization matrix; control charts; cost/benefit analysis; data collection matrix; DOE (design of experiment); FMEA; hypothesis testing; matrix diagrams; PDPC; process maps; Pugh concept evaluation; QFD (quality function deployment); RACI matrix; regression analysis; RWW analysis; solution selection matrix; value stream analysis
- control schemes (DMAIC), 16
- Control step (DMAIC), 15, 24
- controllable design parameters in product robustness development, optimizing, PDF:784-PDF:787
- CoP. *See* communities of practice
- COPQ (cost of poor quality), PDF:763, PDF:922. *See also* quality measures
- correlation  
 in inferential statistics, 694  
 in regression analysis, 596, 598
- correlation analysis in scatter diagrams, 641-643, 647-648. *See also* graphical methods; regression statistical analysis
- correlation charts. *See* scatter diagrams
- cost management, in project management, PDF:809-PDF:810
- cost of poor quality (COPQ), PDF:763, PDF:922. *See also* quality measures
- cost/benefit analysis, 238-242. *See also* SMART
- cost/benefit analysis worksheets, PDF:810
- costs  
 in Quality Loss, PDF:766-PDF:767, PDF:769  
 in Quality Loss Function, PDF:769-PDF:773
- count charts. *See* c-charts
- CPIs (Process Capability Indexes), 488-495
- CPM (Critical Path Method). *See* Activity Network Diagram (AND); WBS (work breakdown structure)
- critical requirements for Fast Track projects, PDF:847-PDF:848
- critical-to-quality (CTQ), 16, 242-247. *See also* cause-and-effect prioritization matrix; conjoint analysis; data collection matrix; matrix diagrams; voice of customer gathering techniques
- cross-functional flowcharts. *See* process maps
- Crystal Ball model, decision variables in, PDF:933
- Crystal Ball software, PDF:935
- CTQ (critical-to-quality), 16, 242-247. *See also* cause-and-effect prioritization matrix; conjoint analysis; data collection matrix; matrix diagrams; voice of customer gathering techniques
- cubic regression, 574

- cumulative sum (CUSUM) charts. *See* control charts
- customer interview guide templates, PDF:811
- customer involvement, PDF:851
- direct involvement, when to use, PDF:851-PDF:852
  - importance
    - to business, PDF:854
    - in determining requirements, PDF:852-PDF:853
    - to product development teams, PDF:856-PDF:857
  - methods for, PDF:860-PDF:867
  - quality function deployment (QFD), usage in, PDF:867-PDF:870
  - timeframes for, PDF:857-PDF:860
- customer relationships, improving, PDF:804-PDF:805
- customer satisfaction templates, PDF:811
- customer support, experiences in, PDF:863-PDF:864
- customer surveys, PDF:863
- customer-pull
  - in CDOV, 53
  - in Lean methodology, 29
- customers
  - becoming, PDF:866-PDF:867
  - determining who is customer, PDF:855-PDF:856
  - joining product development teams, PDF:865
  - Quality Loss examples, PDF:767-PDF:768
  - visiting at workplaces, PDF:865-PDF:866
  - working for, PDF:866
- CUSUM charts. *See* control charts
- cycle time, DMAIC impact on, 14
- D**
- D of E. *See* DOE (design of experiment)
- dashboards, scorecards versus, 654-655. *See also* dotplots
- data collection matrix. 248-250. *See also* ANOVA (analysis of variance); boxplots; brainstorming; control charts; cost/benefit analysis; dotplots; histograms; hypothesis testing; matrix diagrams; MSA; multi-vari charts; Pareto charts; QFD (quality function deployment); regression analysis; run charts; sampling; scatter diagrams
- data collection plans, in sampling, 619
- data integrity, in sampling, 619
- data-driven decision-making, 4
- decision authority matrix, 408-409. *See also* matrix diagrams
- decision matrix, 197. *See also* prioritization matrices; Pugh concept evaluation
- decision processes, PDF:911-PDF:912
- decision variables, in Crystal Ball model, PDF:933
- decisions in product development process, PDF:908-PDF:911
- decision processes, PDF:911-PDF:912
  - gate keepers, PDF:918-PDF:919
  - gate reviews, PDF:914-PDF:917
  - project monitoring, PDF:912-PDF:913
- Define phase
  - IDEA, 73, 78-79
  - CDOV, 60-61
  - DMADV, 50
  - DMAIC, 15, 19-20
- deliverables, Tools-Tasks-Deliverables linkage, 2
- deployment flowcharts. *See* process maps
- descriptive statistics, 684-693
- design concepts in product robustness development, selecting, PDF:783-PDF:784
- design FMEA, 301. *See also* FMEA
- Design for Six Sigma (DFSS), 5. *See also* Six Sigma
- Design of Experiment (DOE), 143, 250-280, 695. *See also* cause-and-effect diagrams; cause-and-effect prioritization matrix; conjoint analysis; QFD (quality function deployment); regression analysis; solution selection matrix
- Design phase
  - CDOV, 54
  - Fast Track project support, PDF:842-PDF:843, PDF:847
  - DMADV, 50
- designed experiments. *See* DOE (design of experiment)
- designing relationships in workplace
  - conscious approach to, PDF:874-PDF:879
  - levels of engagement, PDF:879-PDF:885
- desired-results fishbone diagrams, 187. *See also* cause-and-effect diagrams
- detailed process maps, 525-527. *See also* process maps
- detailed value add matrix, 730-731
- detectable difference, in sampling, 626
- development teams. *See* product development teams
- deviation charts. *See* target charts
- deviation tolerances, in quality measures, PDF:763. *See also* performance variations
- in-spec versus out-of-spec tolerances, PDF:764-PDF:766, PDF:778-PDF:779
  - product development and, PDF:773-PDF:774
  - Quality Loss, PDF:766-PDF:767, PDF:769
  - Quality Loss Function, PDF:769-PDF:773
- DFSS (Design for Six Sigma), 5, 45-66. *See also* Six Sigma
- CDOV method
  - described, 53-54
  - DMADV versus, 55-56
  - objective of, 52
  - process flow, 55
  - steps in, 54-55
- DMADV method
  - components of, 51
  - described, 49-50
  - objective of, 49
  - project duration, 51
  - steps in, 50
- DMAIC versus, 46-47
- evolution of, 45-46
- Loss Function model, 48
- requirements for evaluation, 56-57
- requirements-phase linkage, 58
- robust design principle, 48-49
- tools-tasks-deliverables, 59-64
- variations of, 64-65
- dichotomous questions, in market research, 743
- difference charts. *See* target charts
- digraphs. *See* interrelationship diagrams
- directional tests, non-directional tests versus, 366
- Discontinue phase (LMAD), 97, 109-110
- discovery-based learning, PDF:827-PDF:829
- adult learning theory and, PDF:831-PDF:832
  - advertising goals and, PDF:830-PDF:831

AIDA model, PDF:831  
 complexity of Six Sigma and, PDF:827-PDF:828  
 success of, PDF:832-PDF:833  
 test example, PDF:829-PDF:830  
 dispersion analysis, 175-176, 179-180  
 distribution models, Monte Carlo simulation inputs, PDF:929-PDF:930  
 diversity, leveraging with Six Sigma, project management, and communities of practice, PDF:806-PDF:807  
 DMADV (Define-Measure-Analyze-Design-Validate) method, 5-6, 26. *See also* DFSS  
 CDOV versus, 55-56  
 components of, 51  
 described, 49-50  
 DMAIC versus, 46  
 objective of, 49  
 project duration, 51  
 steps in, 50  
 DMAIC (Define-Measure-Analyze-Improve-Control), 5-6, 13-27  
 business questions answered by, 16-17  
 components of, 16  
 described, 13-16  
 DFSS versus, 46-47  
 duration of projects, 15  
 Fast Track project support, PDF:837-PDF:838  
 icon, 19  
 in marketing, 110  
 measurements in, 25  
 objective of, 13  
 PDSA comparison, 43  
 principles of, 14  
 problem definition in, 25  
 process flow, 17  
 requirements for evaluation, 16-17  
 requirements-step linkage, 18  
 steps in, 15  
 tools-tasks-deliverables  
   for Analyze step, 21-22  
   for Control step, 24  
   for Define step, 19-20  
   for Improve step, 23  
   for Measure step, 20  
 variations in, 26  
 DMAIIC (Define-Measure-Analyze-Improve-Innovate-Control), 5-6, 26-27  
 DMEDI (Define-Measure-Explore-Develop-Implement), 5-6, 65  
 documentation phase (technology development process), PDF:896  
 DOE (Design of Experiment), 143, 250-280, 695.  
*See also* cause-and-effect diagrams;  
 cause-and-effect prioritization matrix;  
 conjoint analysis; QFD (quality function deployment); regression analysis; solution selection matrix  
 dot charts. *See* dotplots  
 dotplots, 280-286, 324, 327. *See also* boxplots;  
 cause-and-effect prioritization matrix;  
 control charts; graphical methods;  
 histograms; statistical tools  
 down-side variance (DSV) (statistics), 691  
 DOWNTIME, 38-39, 729-730  
 durability, performance variations and, PDF:777-PDF:778  
 dynamic processes, sampling, 620

## E

ECO customer requirements, in KJ analysis, 377  
 80/20 rule. *See* Pareto charts  
 engagement  
   in formula for success, PDF:876  
   levels of, PDF:876-PDF:879  
   determining, PDF:879-PDF:881  
   list of, PDF:882-PDF:885  
 error  
   in hypothesis testing, 342-343  
   in regression analysis, 597, 599  
 Evaluate phase (IDEA), 73, 79-80  
 evaluating competition, PDF:861-PDF:862  
 evolution  
   of DFSS, 45-46  
   of Six Sigma, 1  
 EWMA (exponentially weighted moving average) charts. *See* control charts  
 executive reviews, 661  
 experimental techniques. *See* DOE (design of experiment)  
 exponentially weighted moving average (EWMA) charts. *See* control charts  
 external environment, SWOT analysis, 700-701  
 external stress factors, PDF:782  
 extrapolation, in regression analysis, 579, 597

## F

F distribution critical values (ANOVA) (table), 942, 944  
 F-test. *See* ANOVA (analysis of variance)  
 fail-safing. *See* Poka-Yoke  
 failure in fulfilling promises, determining levels of engagement, PDF:880-PDF:881  
 failure modes and effect analysis. *See* FMEA  
 Fast Track projects, PDF:835, PDF:837  
   CDOV support for, PDF:839  
     Concept phase, PDF:839-PDF:842, PDF:847  
     Design phase, PDF:842-PDF:843, PDF:847  
     Optimize phase, PDF:843-PDF:845, PDF:847  
     Verify phase, PDF:845-PDF:848  
   critical requirements, PDF:847-PDF:848  
   DMAIC support for, PDF:837-PDF:838  
   Six Sigma applications for, PDF:836-PDF:837  
   technology development support for, PDF:838-PDF:839  
 fault tree analysis (FTA), 187, 309-316.  
*See also* cause-and-effect diagrams; 5-Whys;  
 risk mitigation plans  
 feedback on current products, PDF:863  
 First Pass Yield (FPY), 495  
 fishbone diagrams. *See* cause-and-effect diagrams; KJ analysis  
 fitted line plots, in scatter diagrams, 649  
 5Ms and P, 175-176. *See also* fault tree analysis;  
 5-Whys; FMEA; risk mitigation plans  
 5W. *See* 5-Whys  
 5W2H, 308-309. *See also* 5-Whys  
 5-Whys, 305-309, 316. *See also* cause-and-effect diagrams; fault tree analysis; FMEA; risk mitigation plans; TRIZ  
 flowcharts. *See* process maps

FMEA (failure modes and effects analysis), 287-304, 315, PDF:810. *See also* ANOVA (analysis of variance); boxplots; brainstorming; cause and prevention matrix; cause-and-effect diagrams; cause-and-effect prioritization matrix; conjoint analysis; control charts; cost/benefit analysis; CTQ (critical-to-quality); DOE (design of experiment); dotplots; fault tree analysis; 5-Whys; GOSPA; graphical methods; hypothesis testing; interrelationship diagrams; matrix diagrams; MPQP; MSA; multi-vari charts; Pareto charts; PDPC; PERT charts; Porter's 5 Forces; process capability analysis; process maps; Pugh concept evaluation; QFD (quality function deployment); RACI matrix; regression analysis; risk mitigation plans; run charts; RWW analysis; scatter diagrams; SWOT; TRIZ; value stream analysis

focus groups, PDF:862-PDF:863

4Ps, 176. *See also* risk mitigation plans

40 inventive principles, 717-722

FPY (First Pass Yield), 495

frequency plots. *See* histograms

FTA (fault tree analysis), 187, 309-316.  
*See also* cause-and-effect diagrams; 5-Whys; risk mitigation plans

full analytical criteria method, 472-480.  
*See also* prioritization matrices

functional decomposition, PDF:784

functional parameter diagrams, PDF:785

functional reviews, 660

## G

Gage R&R analysis, 417, 419, 422-425

Gage Run Chart, 420-422

Gantt charts, 317-319. *See also* WBS (work breakdown structure)

Garvin's eight dimensions of quality, 391

gate keepers, in product development process, PDF:918-PDF:919

gate reviews  
in product development process, PDF:914-PDF:917  
in SSFM, 72

gate symbols (fault tree analysis), prevention strategies for, 313

generating connections (levels of engagement), PDF:883

goal statements, 667

GOSPA (Goals, Objectives, Strategies, Plans, and Actions), 320-323. *See also* MPQP; SWOT

governance process  
gate keepers, PDF:918-PDF:919  
for Six Sigma and project management integration, PDF:822-PDF:824

gradients, in relationships in workplace, PDF:875-PDF:876

graphical methods, 323-329.  
*See also* cause-and-effect prioritization matrix; control charts; data collection matrix; FMEA; MSA; run charts

graphical tools, for statistics, 696-697.  
*See also* hypothesis testing

Green Belts, PDF:816

group charts. *See* control charts

growth goals, achieving with Six Sigma, project management, and communities of practice, PDF:804

## H

HFMEA (healthcare FMEA), 301-303.  
*See also* FMEA

hierarchical diagrams. *See* tree diagrams

high-level process maps, 524-525.  
*See also* process maps

histograms, 324, 330-335. *See also* cause-and-effect diagrams; control charts; dotplots; fault tree analysis; 5-Whys; graphical methods; process capability analysis; run charts; 7QC toolset; statistical tools

bar charts compared, 334  
when to use, 327

history of benchmarking, PDF:791

HOQ (house of quality). *See* QFD (quality function deployment)

Hotelling T2. *See* multivariate charts

human management, in project management, PDF:812

human resources. *See also* relationships in workplace  
for communities of practice, PDF:814-PDF:818, PDF:820  
certification levels, PDF:824-PDF:825  
organizational structure, PDF:820-PDF:822  
resource guidance, PDF:824  
leveraging with Six Sigma, project management, and communities of practice, PDF:805-PDF:806

Human Resources and Community Relations (benchmarking leading practice), PDF:794

hybrid model for Six Sigma and project management integration, PDF:817

hypothesis testing, 335-368, 694. *See also* ANOVA (analysis of variance); cause-and-effect diagrams; cause-and-effect prioritization matrix; control charts; dotplots; fault tree analysis; 5-Whys; histograms; interrelationship diagrams; Pareto charts; sampling

## I

I-MR charts, 223-229. *See also* control charts

icons, DMAIC, 19

ICOV (Identify-Characterize-Optimize-Verify), 5, 65

IDEA (Identify-Define-Evaluate-Activate), 5-6, 73-80  
business goals of, 74-75  
described, 73-74  
Fast Track projects, PDF:836  
phases of, 73  
process flow, 74  
requirements-phase linkage, 76-77  
tools-tasks-deliverables  
for Activate phase, 80  
for Define phase, 78-79  
for Evaluate phase, 79-80  
for Identify phase, 77-78

idea database documentation. *See* RWW analysis

Idea Maps. *See* affinity diagrams

Identify phase (IDEA), 73, 77-78  
 IDOV (Invent-Innovate-Develop-Optimize-Verify), 5-6, 65, PDF:836  
 Implement Many Solutions experimental technique, 255-256  
 implementation plans. *See* cause and prevention matrix; control charts; DOE (design of experiment); FMEA; launch plans; PDPC  
 Improve step (DMAIC), 15, 23  
 in-spec tolerances, out-of-spec tolerances versus, PDF:764-PDF:766, PDF:778-PDF:779  
 inbound marketing, in SSFM, 70-71  
 incentives, PDF:818  
 Individuals control charts. *See* I-MR charts  
 inferential statistics, 693-695  
 influence planning charts, 683  
 informed (RACI matrix), 555  
 Innovation step (DMAIIC), 26  
 innovation strategy. *See* RWW analysis  
 inputs  
   for Monte Carlo simulation, defining, PDF:929-PDF:930  
   required in LMAD, 99-100  
 integration  
   in project management, PDF:813-PDF:814  
   of Six Sigma methods, 6-7  
 intellectual capital. *See* human resources  
 interaction, in regression analysis, 598  
 interaction regression, 574  
 intercept, in regression analysis, 598  
 interdependence, appreciating (levels of engagement), PDF:882  
 interdependency, in hypothesis testing, 343  
 internal environment, SWOT analysis, 702  
 Internal Rate of Return (IRR), 241.  
   *See also* cost/benefit analysis  
 internal stress factors, PDF:782  
 interpolation, in regression analysis, 579, 598  
 interrelationship diagrams, 369-374.  
   *See also* prioritization matrices  
 interrelationship digraphs. *See* 7M toolset  
 interval ranking questions, in market research, 743  
 interval scales, in market research, 745  
 interview guide, for market research, 741-750  
 investment, product development process as, PDF:908  
 IRR (Internal Rate of Return), 241.  
   *See also* cost/benefit analysis  
 Ishikawa diagrams. *See* cause-and-effect diagrams  
 issues and action logs, PDF:813  
 iterative nature of methods, 4  
 IX-MR charts. *See* I-MR charts

**J-K**

Japan, Lean Production in, 30  
 JIT (Just-in-Time), 30  
 job profiles, for Six Sigma and project management integration, PDF:815-PDF:818  
 Kaizen improvements, in Lean methodology, 41-42  
 Kano model  
   in CDOV, 53-54  
   in KJ analysis, 376-378

key milestone reviews, in SSFM, 72  
 KJ analysis, 375-389. *See also* affinity diagrams; benchmarking; MPQP; voice of customer gathering techniques

**L**

L-shape matrix, 402  
 Launch phase  
   LMAD, 97, 104-105  
   UAPL, 83, 94, 96  
 launch plans, 409-410. *See also* benchmarking; matrix diagrams; RWW analysis  
 lead model, for Six Sigma and project management integration, PDF:817  
 leading practices in benchmarking, PDF:789-PDF:795  
 Lean methodology, 29-44  
   business questions answered by, 31  
   described, 30  
   Kaizen improvements, 41-42  
   non-value-added activities, 37-40  
   objective of, 29  
   process flow, 31  
   requirements-step linkage, 32  
   Theory of Constraints (TOC), 40-41  
   tools-tasks-deliverables, 32-36  
   value, defined, 36  
   value-added activities, 36  
   variations of, 42-44  
 Lean Production, 30  
 Lean Six Sigma (LSS). *See also* Six Sigma  
   adaptive nature of, 4  
   in marketing, 110  
   process flow, 44  
   as variation on DMAIC, 26  
 learning. *See* discovery-based learning  
 learning continuum for Six Sigma and project management integration, PDF:819-PDF:820  
 left-tail test (Z values), 945  
   in hypothesis testing, 340  
 lessons learned templates, PDF:814  
 Likert rating scale in market research, 745  
 line graphs, 324. *See also* run charts  
 linear regression, 574, 598. *See also* regression analysis; simple linear regression  
 linear relationships, in scatter diagrams, 641-643, 647-648  
 LMAD (Launch-Manage-Adapt-Discontinue), 6, 97-110  
   business questions, 100-101  
   common tool set, 102-104  
   described, 97-99  
   inputs required, 99-100  
   phases of, 97  
   process flow, 99  
   requirements-milestone linkage, 101-102  
   tools-tasks-deliverables, 104-110  
 logistic ordinal regression, 598  
 logistic regression, 575. *See also* regression analysis  
 Loss Function model, in DFSS, 48  
 loss of quality. *See* Quality Loss  
 LSS (Lean Six Sigma). *See* Lean Six Sigma (LSS)

**M**

- MA-MR (moving average-moving range) charts.  
*See* control charts
- Manage phase (LMAD), 97, 106-107
- management quality review and checklist, PDF:811
- market behavioral dynamics mapping. *See* RWW analysis
- market definition. *See* RWW analysis
- market perceived quality profile (MPQP), 390-399
- market research, 739, PDF:860-PDF:861  
 in advanced product planning, PDF:858  
 interview guide, 741-750
- marketing, DMAIC and Lean Six Sigma in, 110.  
*See also* SSFM (Six Sigma for Marketing)
- marketing tasks, in Concept phase (CDOV) for Fast Track projects, PDF:840
- Master Black Belts, PDF:816
- master-apprentice relationship, PDF:800
- matrix diagrams, 399-411. *See also* Activity Network Diagram (AND); affinity techniques; ANOVA (analysis of variance); benchmarking; brainstorming; cause and prevention matrix; cause-and-effect prioritization matrix; control charts; cost/benefit analysis; data collection matrix; DOE (design of experiment); FMEA; hypothesis testing; KJ analysis; MPQP; PDPC; prioritization matrices; process maps; Pugh concept evaluation; QFD (quality function deployment); RACI matrix; regression analysis; RWW analysis; 7M toolset; SMART; solution selection matrix; value stream analysis
- matrix plots, in scatter diagrams, 650-651
- matrix relations diagrams. *See* interrelationship diagrams
- mean (statistics), 684
- Measure step  
 DMADV, 50  
 DMAIC, 15, 20
- measurement system (DMAIC), 16
- measurement system analysis (MSA), 412-430.  
*See also* sampling  
 in market research, 747  
 for statistics, 697
- measurement system evaluation method.  
*See* MSA (measurement system analysis)
- measurements, in DMAIC, 25
- median (statistics), 685
- meeting agenda templates, PDF:812
- meeting minutes templates, PDF:812
- methodology for Six Sigma and project management integration, selecting, PDF:807-PDF:814
- methods  
 adaptive nature of, 3  
 defined, 1  
 integration of, 6-7  
 iterative nature of, 4  
 operational-based, 5-6  
 project-based, 4-5
- milestone charts. *See* Gantt charts
- mind-mapping. *See* brainstorming
- minimum requirements in Fast Track projects (CDOV)  
 Concept phase, PDF:841-PDF:842, PDF:847  
 Design phase, PDF:843, PDF:847  
 Optimize phase, PDF:844-PDF:845, PDF:847  
 Verify phase, PDF:846-PDF:848
- mistake-proofing. *See* Poka-Yoke
- mode (statistics), 685
- monitoring projects, PDF:912-PDF:913
- Monte Carlo simulations, 431-439. *See also* Gantt charts; histograms; solution selection matrix  
 as project selection method, PDF:924-PDF:929  
 inputs, defining, PDF:929-PDF:930  
 outputs, defining, PDF:930-PDF:931  
 sensitivity analysis of, PDF:931-PDF:932  
 stochastic optimization, PDF:932-PDF:935
- moving average-moving range charts. *See* control charts
- moving range. *See* I-MR charts
- MPQP (market perceived quality profile), 390-399. *See also* RWW analysis; SWOT
- MSA (measurement system analysis), 412-430.  
*See also* sampling  
 in market research, 747  
 for statistics, 697
- multi-vari charts, 324, 327, 439-443.  
*See also* cause-and-effect prioritization matrix; graphical methods
- multi-vari plots. *See* multi-vari charts
- multi-vari studies. *See* multi-vari charts
- multiple characteristic charts. *See* group charts
- multiple choice questions, in market research, 744
- multiple linear regression, 599
- multiple regression, 574, 582-594.  
*See also* regression analysis
- multiple response questions, in market research, 744
- multiplicative law of probability, 696
- multivariate charts. *See* control charts

**N**

- negative slope, in regression analysis, 600
- Net Present Value (NPV), 240.  
*See also* cost/benefit analysis
- network diagrams. *See* Activity Network Diagram (AND); interrelationship diagrams
- node diagrams. *See* Activity Network Diagram (AND)
- noise diagrams. *See* DOE (design of experiment)
- nominal charts. *See* target charts
- nominal group technique. *See* brainstorming
- non-comparative scales, in market research, 744
- non-directional tests, directional tests versus, 366
- non-linear regression, 574-575
- non-linear relationships, in scatter diagrams, 643-644
- non-normal data transformations (Box-Cox transformations), 228-229
- non-value-added activities, in Lean methodology  
 defined, 37  
 types of, 37-39  
 waste elimination strategies, 39-40
- normal distribution (statistics), 687-688
- normal probability plots, 227-228. *See also* control charts; process capability analysis
- np-charts, 233-234. *See also* control charts

NPV (Net Present Value), 240.

*See also* cost/benefit analysis

NUD (New, Unique, and Difficult) elements  
in CDOV, 53-54

customer requirements in KJ analysis, 376  
null hypothesis, 338, 352

## O

OFAT (one factor at a time) experimental  
technique, 253-254

offering pipe-line planning and activation.  
*See* RWW analysis

one sample t-test, example of, 353-356

one-tail tests, in hypothesis testing, 339

one-way ANOVA. *See* ANOVA (analysis of  
variance)

open-ended questions, in market research,  
741-742

operational models, data analysis, and controls  
tool set (LMAD), 103-104

operational-based methods, 5-6

optimization. *See* stochastic optimization

Optimize phase (CDOV), 54, 62-63

Fast Track project support  
minimum requirements, PDF:844-PDF:845,  
PDF:847

risk characteristics, PDF:843-PDF:844

ordinal scales, in market research, 745

organizational structure for Six Sigma and project  
management integration, PDF:820-PDF:822

out-of-spec tolerances, in-spec tolerances versus,  
PDF:764-PDF:766, PDF:778-PDF:779

outbound marketing, in SSFM, 70-73

outputs for Monte Carlo simulation, defining,  
PDF:930-PDF:931

## P

P Prime SPC charts, 233. *See also* control charts

p-charts, 232-233. *See also* control charts

p-value

in hypothesis testing, 341

in regression analysis, 578-579

PACE (Product and Cycle time Excellence),  
PDF:888

paired t-test, example of, 356-360  
parameters

in inferential statistics, 693

in sampling, 619

Pareto analysis, as project selection method,  
PDF:922

Pareto charts, 324, 328, 331, 445-452. *See also*  
cause-and-effect diagrams; fault tree  
analysis; 5-Whys; graphical methods; 7QC  
toolset; statistical tools

passive data collection, 739

payback period, 241

PDCA (Plan-Do-Check-Act), 5, 42

PDM (Precedence Diagram). *See* Activity  
Network Diagram (AND)

PDPC (process decision program charts),  
515-521. *See also* risk mitigation plans;  
7M toolset

PDSA (Plan-Do-Study-Act), 5

DMAIC comparison, 43

as variation of Lean methodology, 42

Pearson's coefficient of skewness, 692

Pearson's Correlation Coefficient (r), 597, 642

pedagogy, PDF:832

people. *See* human resources; relationships in  
workplace

percentage charts. *See* p-charts

performance. *See* quality measures

performance charts. *See* dotplots; histograms;  
hypothesis testing; multi-vari charts; Pareto  
charts; run charts; scatter diagrams; SWOT

performance development phase (technology  
development process), PDF:895

performance indices, in benchmarking,  
PDF:792-PDF:793

performance variation. *See also* deviation  
tolerances; Quality Loss; Quality Loss  
Function

cause-and-effect analyses, PDF:779-PDF:780

in product development, PDF:777-PDF:779

robustness development, PDF:780-PDF:781  
controllable design parameters, optimizing,  
PDF:784-PDF:787

design concepts, selecting, PDF:783-PDF:784

stress factors, identifying, PDF:781, PDF:783

PERT (Program Evaluation and Review

Technique) charts, 453-461. *See also* Activity  
Network Diagram (AND); QFD (quality  
function deployment); WBS (work  
breakdown structure)

PEST (Political, Economic, Social, and  
Technological) analysis, 701

PFQT (productivity, financial, quality, time),  
13, 25

phase-gate reviews, in Six Sigma and project  
management integration, PDF:823-PDF:824.  
*See also* cost/benefit analysis

phase-gate structure

CDOV, 54

DMADV, 50

PIDOV (Plan-Identify-Design-Optimize-  
Validate), 5, 65

pie charts, 325

pilot plans. *See* launch plans; solution selection  
matrix

Plan phase (UAPL), 83, 92

PM. *See* project management

PMI (Project Management Institute),  
PDF:802-PDF:803

Poisson distribution (statistics), 691

Poka-Yoke, 462-464. *See also* matrix diagrams

political choices, as project selection method,  
PDF:924

population sampling, 618, 620-621

Porter's 5 Forces, 464-470. *See also* MPQP; RWW  
analysis; SWOT

portfolio. *See* project portfolio

portfolio architecting, ranking, and balancing.  
*See* RWW analysis

portfolio risk analysis. *See* RWW analysis

portfolio selection. *See* project selection methods

portfolio strategic plan. *See* SWOT

positive slope, in regression analysis, 599

Post-Launch Operational Management process,  
in SSFM, 70-71

post-launch operational processes, in LMAD, 97

post-launch reviews, in production development  
process, PDF:907

power

in formula for success, PDF:876

in hypothesis testing, 342

- Precedence Diagram (PDM). *See* Activity Network Diagram (AND)
- precision, accuracy versus, 413-415
- prerequisites for CDOV, 56-57
- primary customer research, 739
- principles of Six Sigma
- adaptive nature of methods, 3
  - data-driven decision-making, 4
  - iterative nature of methods, 4
  - operational-based methods, 5-6
  - process-centric view, 3
  - project-based methods, 4-5
  - result-metrics focus, 3
- Tools-Tasks-Deliverables linkage, 2
- prioritization matrices, 470-485. *See also* cause-and-effect prioritization matrix; matrix diagrams; Porter's 5 Forces; 7M toolset; solution selection matrix
- probability, 603, 695-696
- probability distributions. *See* Monte Carlo simulation
- probing questions, in market research, 742
- problem definition, in DMAIC, 25
- problem statements, 666
- process behavior charts. *See* control charts
- process capability analysis, 486-515. *See also* MSA
- Process Capability Indexes (CPIs), 488-495
- process capability study. *See* process capability analysis
- process classification analysis, 176, 179-181
- process decision program charts (PDPC), 515-521
- process definition tool set (LMAD), 102-103
- process fishbone diagrams, 187. *See also* cause-and-effect diagrams
- process FMEA, 303-304. *See also* FMEA
- process improvement methodology. *See* DMAIC
- process innovation methodology. *See* DMADV
- process maps, 522-533. *See also* ANOVA (analysis of variance); cause-and-effect diagrams; cause-and-effect prioritization matrix; CTQ (critical-to-quality); data collection matrix; DOE (design of experiment); fault tree analysis; 5-Whys; FMEA; hypothesis testing; MSA; PDPC; PERT charts; RACI matrix; 7QC toolset; SMART; value stream analysis
- Process Planning QFD matrix, 545
- process risk management tool set (LMAD), 103
- process sampling, 621-622
- process tools for statistics, 697
- Process-based RACI matrix, 555
- process-centric view, 3
- processes, defined, 1, 70
- procurement contract templates, PDF:813
- procurement management, in project management, PDF:813
- procurement management plan checklist, PDF:813
- producers, Quality Loss examples, PDF:768
- product development, performance variations and, PDF:773-PDF:774, PDF:777-PDF:779
- product development process
- adapting for specific projects, PDF:897-PDF:898
  - advanced product planning process in, PDF:891-PDF:894
  - advantages of, PDF:887-PDF:888
  - decisions in, PDF:908-PDF:911
  - decision processes, PDF:911-PDF:912
  - gate keepers, PDF:918-PDF:919
  - gate reviews, PDF:914-PDF:917
  - project monitoring, PDF:912-PDF:913
  - examples of, PDF:888-PDF:889
  - as investment, PDF:908
  - phases, description of, PDF:901-PDF:907
  - post-launch reviews, PDF:907
  - project portfolio, PDF:889-PDF:891
  - structure of, PDF:899-PDF:901
  - technology development process in, PDF:894-PDF:895, PDF:897
- product development teams
- customer involvement, PDF:851
  - direct involvement, when to use, PDF:851-PDF:852
  - importance in determining requirements, PDF:852-PDF:853
  - importance to business, PDF:854
  - importance to teams, PDF:856-PDF:857
  - methods for, PDF:860-PDF:867
  - quality function deployment (QFD), usage in, PDF:867-PDF:870
  - timeframes for, PDF:857-PDF:860
- customers, determining who is customer, PDF:855-PDF:856
- product FMEA, 304. *See also* FMEA
- Product Planning QFD matrix, 545. *See also* QFD (quality function deployment)
- product quality, in MPQP, 391
- product reliability
- perceptions of, PDF:765
  - performance variations and, PDF:777-PDF:778
- product robustness, PDF:774
- cause-and-effect analysis, PDF:779-PDF:780
- development of, PDF:780-PDF:781
- controllable design parameters, optimizing, PDF:784-PDF:787
  - design concepts, selecting, PDF:783-PDF:784
  - stress factors, identifying, PDF:781, PDF:783
- performance variations and, PDF:778
- product service departments, experiences in, PDF:863-PDF:864
- products, Quality Loss, PDF:766-PDF:767, PDF:769
- professionalism of team, PDF:818
- Program Evaluation and Review Technique (PERT) charts. *See* Activity Network Diagram (AND); PERT charts
- program managers, PDF:802, PDF:816
- program offices, PDF:820-PDF:821
- project bar charts. *See* Gantt charts
- project budget worksheets, PDF:810
- project change request forms, PDF:809
- project charters, 667-670. *See also* cost/benefit analysis; GOSPA; PDPC; WBS (work breakdown structure)
- project close-out team questionnaires, PDF:812
- project clustering, as project selection method, PDF:923
- project coordinators, PDF:815
- project directories, PDF:812
- project management, PDF:799, PDF:801-PDF:803, PDF:815
- best practices, PDF:803
  - combined with Six Sigma and communities of practice, PDF:804-PDF:807
  - elements of, PDF:808
  - communication management, PDF:811-PDF:812
  - cost management, PDF:809-PDF:810

human management, PDF:812  
 integration, PDF:813-PDF:814  
 procurement management, PDF:813  
 quality management, PDF:811  
 risk management, PDF:810-PDF:811  
 scope management, PDF:809  
 time management, PDF:809

Six Sigma integration  
 certification levels, PDF:824-PDF:825  
 governance process, PDF:822-PDF:824  
 human resources, PDF:814-PDF:818, PDF:820  
 organizational structure, PDF:820-PDF:822  
 resource guidance, PDF:824  
 selecting methodology, PDF:807-PDF:814  
 terminology, PDF:802

Project Management Institute (PMI),  
 PDF:802-PDF:803

project manager evaluation forms, PDF:812  
 project monitoring, PDF:912-PDF:913  
 project notebook templates, PDF:813  
 project phase-gate reviews. *See* phase-gate reviews  
 project planning tools. *See* QFD (quality function deployment)  
 project plans. *See* Gantt charts  
 project portfolio  
 in product development process, PDF:889-PDF:891  
 in Six Sigma and project management integration, PDF:822-PDF:823  
 project prioritization matrix, as project selection method, PDF:923  
 project responsibility matrix, PDF:812  
 project schedule tools and templates, PDF:809  
 project selection methods, PDF:921-PDF:922  
 aerospace R&D example, PDF:927-PDF:928  
 Cost of Poor Quality (COPQ), PDF:922  
 Monte Carlo simulation, PDF:924-PDF:929  
 inputs, defining, PDF:929-PDF:930  
 outputs, defining, PDF:930-PDF:931  
 sensitivity analysis of, PDF:931-PDF:932  
 stochastic optimization and, PDF:932-PDF:935  
 Pareto analysis, PDF:922  
 political choices, PDF:924  
 project clustering, PDF:923  
 project prioritization matrix, PDF:923  
 quality function deployment (QFD), PDF:923  
 in Six Sigma and project management integration, PDF:822-PDF:823  
 theory of constraints (TOC), PDF:924  
 value-based management, PDF:923  
 project sponsors, phase-gate reviews, PDF:823  
 project staffing request forms, PDF:812  
 project status reports, PDF:812  
 project team organization charts, PDF:812.  
*See also* SMART

project-based methods, 4-5  
 Project-based RACI matrix, 555  
 projective techniques, for probing questions, 742  
 proportion charts. *See* p-charts  
 prototype testing, PDF:864-PDF:865  
 Pugh concept evaluation, 534-542. *See also*  
 cause-and-effect prioritization matrix;  
 conjoint analysis; matrix diagrams; MPQP;  
 prioritization matrices; RWW analysis;  
 solution selection matrix; TRIZ

Pugh concept generation, PDF:912  
 Pugh matrix. *See* Pugh concept evaluation

## Q

QFD (quality function deployment). *See* quality function deployment (QFD)

quadratic regression, 574

Quality Control QFD matrix, 545

quality function deployment (QFD), 197, 543-553.  
*See also* ANOVA (analysis of variance); benchmarking; boxplots; brainstorming; cause-and-effect diagrams; cause-and-effect prioritization matrix; conjoint analysis; CTQ (critical-to-quality); DOE (design of experiment); dotplots; fault tree analysis; 5-Whys; graphical methods; hypothesis testing; interrelationship diagrams; KJ analysis; matrix diagrams; MPQP; multi-vari charts; Pareto charts; process capability analysis; Pugh concept evaluation; TRIZ; voice of customer gathering techniques  
 customer involvement in, PDF:867-PDF:870  
 as project selection method, PDF:923

Quality Loss, PDF:766-PDF:767, PDF:769

Quality Loss Function, PDF:769-PDF:773

quality management, in project management, PDF:811

quality measures, tolerance for deviation, PDF:763. *See also* performance variations  
 in-spec versus out-of-spec tolerances, PDF:764-PDF:766, PDF:778-PDF:779  
 product development and, PDF:773-PDF:774  
 Quality Loss, PDF:766-PDF:767, PDF:769  
 Quality Loss Function, PDF:769-PDF:773

quota sampling, 625

## R

R-Square-adjusted, in regression analysis, 577-578

RACI (responsible, accountable, consulted, informed) matrix, 554-560, PDF:910.  
*See also* matrix diagrams; SMART; WBS (work breakdown structure)

random number generation, in sampling, 638-639

random population sampling, 623

range (statistics), 686

ranking questions, in market research, 743

RAPID analysis, for decisions, PDF:910-PDF:911

rating scales, in market research, 744

ratio ranking questions, in market research, 743

ratio scales, in market research, 745

Real-Win-Worth (RWW) analysis, 560-571.  
*See also* matrix diagrams; Pugh concept evaluation; solution selection matrix; SWOT

recognizing myself (levels of engagement), PDF:882

recruitment programs, PDF:818

reducing variation with DMAIC, 13

regression analysis, 571-600. *See also* cause-and-effect diagrams; cause-and-effect prioritization matrix; control charts; dotplots; fault tree analysis; 5-Whys; interrelationship diagrams; Pareto charts; scatter diagrams  
 in inferential statistics, 694  
 in scatter diagrams, 643-644

regression lines, 599, 649

regression models, 599

- relationship diagrams. *See* interrelationship diagrams
- relationships in workplace, PDF:873-PDF:874
- conscious approach to, PDF:874-PDF:876, PDF:878-PDF:879
- levels of engagement
- determining, PDF:879-PDF:881
  - list of, PDF:882-PDF:885
- reliability. *See* product reliability
- representative sampling, 619-620
- requirement matrix. *See* quality function deployment (QFD)
- requirements
- business goals of IDEA, 74-75
  - business questions
    - answered by DMAIC, 16-17
    - answered by Lean methodology, 31
    - in LMAD, 100-101
    - UAPL, 84
  - determining with customer involvement, PDF:852-PDF:853
    - for DFSS evaluation, 56-57
    - for DMAIC evaluation, 16-17
    - LMAD, inputs required, 99-100
- requirements clarification phase (technology development process), PDF:895
- requirements-milestone linkage (LMAD), 101-102
- requirements-phase linkage
- DFSS, 58
  - DMAIC, 18
  - IDEA, 76-77
  - Lean methodology, 32
  - UAPL, 84, 86
- residual, in regression analysis, 597, 599
- resource guidance for Six Sigma and project management integration, PDF:824
- resources. *See* human resources
- responsibility, in formula for success, PDF:876
- responsibility charts. *See* RACI matrix
- responsible (RACI matrix), 555
- result-metrics focus, 3
- Return on Assets (ROA), 240. *See also* cost/benefit analysis
- Return on Investment (ROI), 240. *See also* cost/benefit analysis
- reverse fishbone diagrams, 187-188. *See also* cause-and-effect diagrams
- review scorecards, 660-662
- right-tail test (Z values), 339, 948
- risk, defined, 603
- risk analysis tools, PDF:810
- risk characteristics, in CDOV Fast Track projects
  - Concept phase, PDF:839-PDF:841
  - Design phase, PDF:842-PDF:843
  - Optimize phase, PDF:843-PDF:844
  - Verify phase, PDF:845-PDF:846
- risk control phase (risk management), 609
- risk event assessment forms, PDF:810
- risk filter processes, PDF:811
- risk identification phase (risk management), 603-605
- risk management. *See also* risk mitigation plans
- defined, 603
  - phases of, 603-609
  - in project management, PDF:810-PDF:811
- risk mitigation plans, 601-610, PDF:810. *See also* cause and prevention matrix; control charts; cost/benefit analysis; DOE (design of experiment)
- Risk Opportunity Analysis Model (ROAM), PDF:810
- Risk Priority Number (RPN), 297
- risk quantification phase (risk management), 605-607
- risk response phase (risk management), 607-608
- risk watch lists, PDF:811
- ROA (Return on Assets), 240. *See also* cost/benefit analysis
- ROAM (Risk Opportunity Analysis Model), PDF:810
- robust design principle, in DFSS, 48-49
- robustness. *See* product robustness
- robustness development phase (technology development process), PDF:896
- ROI (Return on Investment), 240. *See also* cost/benefit analysis
- roles and responsibilities charts. *See* RACI matrix
- Rolled Throughput Yield (RTY), 495. *See also* process capability analysis
- roof-shaped matrix, 403
- root cause analysis. *See* CTQ (critical-to-quality); dotplots; fault tree analysis; 5-Whys; hypothesis testing; interrelationship diagrams; process capability analysis; regression analysis
- round-robin brainstorming. *See* brainstorming
- RPN (Risk Priority Number), 297
- RTY (Rolled Throughput Yield), 495. *See also* process capability analysis
- run charts, 325, 328, 610-614. *See also* graphical methods; process capability analysis; 7QC toolset; SMART; statistical tools
- RWW (Real-Win-Worth) analysis, 560-571. *See also* matrix diagrams; Pugh concept evaluation; solution selection matrix; SWOT

## S

- salaries, PDF:818
- sales. *See* marketing
- sample size, 625-628
  - calculating, 628-638
- sample statistics, in inferential statistics, 693
- sampling, 618-639. *See also* regression analysis
- sampling error, defined, 620
- scatter diagrams, 325, 640-653. *See also* cause-and-effect prioritization matrix; graphical methods; regression analysis; 7QC toolset; statistical tools
  - in regression analysis, 594-599
  - when to use, 328
- scope management, in project management, PDF:809
- scorecards, 653-663
- secondary customer research, 739
- seed strategies, PDF:818
- segmentation, stratification versus, 698
- segmentation and opportunity identification. *See* RWW analysis
- selecting
  - projects. *See* project selection methods
  - tools, 7-8
- self-selected sampling, 625
- Semantic Differential scale, in market research, 745
- sensitivity analysis, of Monte Carlo simulations, PDF:931-PDF:932

- service FMEA. *See* process FMEA; product FMEA
- service quality, in MPQP, 391
- 7M toolset, 130, 137, 370, 403, 517, 615-616, 713.  
*See also* 7QC toolset
- 7MP toolset. *See* 7M toolset
- 7QC toolset, 174, 204, 331, 446, 611, 616-617, 644, 699. *See also* 7M toolset
- shape (in descriptive statistics), 687-692
- short run charts. *See* control charts
- significance level, in hypothesis testing, 341
- simple linear regression, 580-582, 599
- simple matrix. *See* matrix diagrams
- SIPOC (Supplier-Input-Process-Output-Customer), 663-665. *See also* matrix diagrams; process maps; SMART; WBS (work breakdown structure)
- 6Ms. *See* 5Ms and P; risk mitigation plans
- Six Sigma  
combined with project management and communities of practice, PDF:804-PDF:807  
complexity of, PDF:827-PDF:828  
contexts of, PDF:873  
evolution of, 1  
methods, integration of, 6-7  
principles  
adaptive nature of methods, 3  
data-driven decision-making, 4  
iterative nature of methods, 4  
operational-based methods, 5-6  
process-centric view, 3  
project-based methods, 4-5  
result-metrics focus, 3  
Tools-Tasks-Deliverables linkage, 2  
project management integration  
certification levels, PDF:824-PDF:825  
governance process, PDF:822-PDF:824  
human resources, PDF:814-PDF:818, PDF:820  
organizational structure, PDF:820-PDF:822  
resource guidance, PDF:824  
selecting methodology, PDF:807-PDF:814  
project selection methods. *See* project selection methods
- Six Sigma for Marketing. *See* SSFM (Six Sigma for Marketing)
- skewness (statistics), 691
- skills assessment, PDF:819
- SLEPT (Social, Legal, Economic, Political, and Technological) analysis, 701
- slope, in regression analysis, 599
- SMART, 665-672. *See also* cost/benefit analysis; GOSPA; PDPC
- solution impact diagrams. *See* reverse fishbone diagrams
- solution selection matrix, 672-680. *See also* ANOVA (analysis of variance); conjoint analysis; hypothesis testing; matrix diagrams; MPQP; prioritization matrices; Pugh concept evaluation; QFD (quality function deployment)
- Solutions House (learning company), PDF:833
- SOP (standard operating procedures).  
*See* cause and prevention matrix; CTQ (critical-to-quality); data collection matrix; DOE (design of experiment); process maps; value stream analysis
- SPC (statistical process control) charts.  
*See* control charts
- special cause variation (statistics), 686
- splines technique, in regression analysis, 575
- SSFM (Six Sigma for Marketing), 5, 10, 67-111.  
*See also* Six Sigma  
additional resources for information, 111  
described, 68  
IDEA. *See* IDEA  
inbound marketing, 70-71  
LMAD. *See* LMAD  
objective of, 67-68  
outbound marketing, 70-73  
Post-Launch Operational Management process, 70-71  
Strategic Planning and Portfolio Renewal process, 69  
Strategic-Tactical-Operational triangle, 69  
Tactical Planning and Portfolio Renewal process, 69  
UAPL. *See* UAPL
- stabilized charts. *See* short run charts
- staged deployment of SSFM, 73
- stakeholder analysis, 680-683
- stakeholders, 668
- standard deviation (statistics), 626, 687
- standard normal distribution (statistics), 688-690
- standard normal table (Z values)  
left-tail test, 945  
right-tail test, 948
- standard operating procedures (SOP).  
*See* cause and prevention matrix; CTQ (critical-to-quality); data collection matrix; DOE (design of experiment); process maps; value stream analysis
- standard toolset (DMAIC), 16
- State-Gate, PDF:888
- static populations, sampling, 620
- statistical analysis. *See* dotplots
- statistical distribution tables  
chi-square distribution critical values, 941  
F distribution critical values (ANOVA), 942, 944  
standard normal table (Z values)  
left-tail test, 945  
right-tail test, 948  
t distribution critical values, 939-940
- statistical process control (SPC) charts.  
*See* control charts
- statistical tools, 684-697. *See also* boxplots; graphical methods; MSA; multi-vari charts; Pareto charts; sampling
- STEEPLE (Social/demographic, Technological, Economic, Environmental (natural), Political, Legal, and Ethical) analysis, 701
- stem-and-leaf, 325. *See also* graphical methods
- Stick with a Winner experimental technique, 254-255
- stochastic optimization, Monte Carlo simulation and, PDF:932-PDF:935
- Strategic Planning and Portfolio Renewal process, in SSFM, 69
- strategic planning process, benchmarking in, PDF:794-PDF:795
- Strategic-Tactical-Operational triangle, in SSFM, 69
- stratification, 697-699. *See also* 7QC toolset; statistical tools
- stratified dot plots. *See* dotplots
- stratified random population sampling, 623-624
- stress factors in product robustness development, identifying, PDF:781, PDF:783

student t-distribution (statistics), 690  
 subgroup process sampling, 624  
 success, formula for, PDF:875-PDF:876  
 summary value add matrix, 730-731  
 Supply Chain Management (benchmarking leading practice), PDF:794  
 surveys, customer surveys, PDF:863  
 swim-lane process maps. *See* process maps  
 SWOT (Strengths-Weaknesses-Opportunities-Threats), 699-711. *See also* MPQP; Porter's 5 Forces; Pugh concept evaluation; QFD (quality function deployment); RWW analysis; solution selection matrix  
 systematic diagrams. *See* tree diagrams  
 systematic process sampling, 623-624  
 systems FMEA, 304. *See also* FMEA

## T

t distribution critical values (table), 939-940  
 T-shape matrix, 402  
 t-test. *See also* hypothesis testing  
   one sample t-test, example of, 353-356  
   paired t-test, example of, 356-360  
 tables. *See* matrix diagrams  
 Tactical Planning and Portfolio Renewal process, in SSFM, 69  
 target charts. *See* control charts  
 task scorecards, 658-660  
 tasks, Tools-Tasks-Deliverables linkage, 2  
 team leaders, PDF:818  
 teams. *See* product development teams  
 technology development process, PDF:838-PDF:839, PDF:894-PDF:897  
 Test at Extremes experimental technique, 255-256  
 test example (discovery-based learning), PDF:829-PDF:830  
 test for equal variances. *See* ANOVA (analysis of variance)  
 test statistics, in hypothesis testing, 338  
 testing, prototype testing, PDF:864-PDF:865  
 Theory of Constraints (TOC), 40-41, PDF:924  
 3C litmus test (Lean methodology), for value-added activities, 36  
 time management, in project management, PDF:809  
 time plots. *See* run charts  
 time series plots. *See* run charts  
 time-based value add analysis, 732  
 time-delay fishbone diagrams, 188.  
   *See also* cause-and-effect diagrams  
 timeframes for customer involvement, PDF:857-PDF:860  
 TOC (Theory of Constraints), 40-41, PDF:924  
 tolerance for deviation in quality measures, PDF:763. *See also* performance variations  
   in-spec versus out-of-spec tolerances, PDF:764-PDF:766, PDF:778-PDF:779  
   product development and, PDF:773-PDF:774  
   Quality Loss, PDF:766-PDF:767, PDF:769  
   Quality Loss Function, PDF:769-PDF:773  
 tool scorecards, 655-658  
 tool set (LMAD), 102-104  
 tools  
   selecting, 7-8  
   Tools-Tasks-Deliverables linkage, 2

tools-tasks-deliverables  
 DFSS, 59-64  
 DMAIC, 19-24  
 IDEA, 77-80  
 Lean methodology, 32-36  
 LMAD, 104-110  
 UAPL, 87-96  
 Tools-Tasks-Deliverables linkage, 2  
 Toyota, Lean Production at, 30  
 training, discovery-based learning.  
   *See* discovery-based learning  
 training plans. *See* process maps; value stream analysis  
 transformation of non-normal data (Box-Cox transformations), 228-229  
 transition plans, 410-411. *See also* benchmarking; cause and prevention matrix; control charts; DOE (design of experiment); FMEA; matrix diagrams; PDPC; Pugh concept evaluation; solution selection matrix  
 tree analysis. *See* tree diagrams  
 tree diagrams, 712-715. *See also* Activity Network Diagram (AND); affinity diagrams; affinity techniques; brainstorming; interrelationship diagrams; KJ analysis; 7M toolset  
 TRIZ, 715-726  
 two-tailed tests, in hypothesis testing, 340  
 two-way ANOVA with replicates. *See* ANOVA (analysis of variance)  
 two-way ANOVA without replicates.  
   *See* ANOVA (analysis of variance)  
 Type I error, in sampling, 626  
 Type II error, in sampling, 626

## U

u-charts, 235-236. *See also* control charts  
 UAPL (Understand-Analyze-Plan-Launch), 5-6, 52, 81-96  
   business questions, 84  
   concept strategy inputs, 83  
   described, 81-83  
   phases of, 82  
   process flow, 83  
   requirements-phase linkage, 84, 86  
   tools-tasks-deliverables  
     Analyze phase, 90-91  
     Launch phase, 94, 96  
     Plan phase, 92  
     Understand phase, 87, 89  
 uncertainty, defined, 603  
 Understand phase (UAPL), 82, 87, 89  
 unit charts. *See* u-charts  
 unit-to-unit stress factors, PDF:782

## V

Validate step (DMADV), 50  
 value, in Lean methodology, 36  
 value propositions, PDF:853, PDF:857-PDF:858  
 value stream analysis, 727-737. *See also* PERT charts; process maps  
 value stream mapping (VSM), 735-737.  
   *See also* value stream analysis  
 value-added activities, in Lean methodology, 29, 36

- value-based management, as project selection method, PDF:923
- variables, in regression analysis, 600
- variance (statistics), 686-687
- variations. *See also* performance variations
  - in descriptive statistics, 685-687
  - of DFSS, 64-65
  - of DMAIC, 26-27
  - of Lean methodology, 42-44
  - reducing with DMAIC, 13
- Verify phase (CDOV), 54, 63-64, PDF:845-PDF:848
- vision, in formula for success, PDF:876
- visiting customers at workplaces, PDF:865-PDF:866
- VOB (voice of business) requirements. *See* voice of customer gathering techniques
- VOC (voice of customer). *See* voice of customer gathering techniques; customer involvement
- voice of customer gathering techniques, 737-752. *See also* Activity Network Diagram (AND); affinity diagrams; benchmarking; cause-and-effect diagrams; cause-and-effect prioritization matrix; conjoint analysis; CTQ (critical-to-quality); customer involvement; fault tree analysis; 5-Whys; FMEA; Gantt charts; GOSPA; KJ analysis; MPQP; PDPC; Pugh concept evaluation; QFD (quality function deployment); RWW analysis; solution selection matrix; SWOT
- VSM (value stream mapping), 735-737. *See also* value stream analysis

Y = f (X), 758-759  
 Y-shape matrix, 402  
 Yellow Belts, PDF:816

Z values
 

- left-tail test, 945
- right-tail test, 948

 Z-charts. *See* short run charts  
 Z-test. *See* hypothesis testing

## W

- waste. *See also* non-value-added activities in Lean methodology
  - categories of, 729-730
  - elimination strategies in Lean methodology, 39-40
- WBS (work breakdown structure), 753-757, PDF:813. *See also* tree diagrams
- weighted Pareto analysis, 452. *See also* Pareto charts
- Why-Why. *See* 5-Whys
- won/loss analysis. *See* SWOT
- work breakdown structure (WBS), 753-757, PDF:813. *See also* tree diagrams
- workflow diagrams. *See* process maps
- working for customers, PDF:866
- workplace relationships. *See* relationships in workplace
- written reports. *See* interrelationship diagrams

## X-Z

- X-bar and R charts, 229-230. *See also* control charts
- X-bar and S charts, 230-231. *See also* control charts
- X-charts. *See* I-MR charts
- X-R charts. *See* I-MR charts
- X-shape matrix, 403
- X-Y graphs. *See* scatter diagrams
- XmR. *See* I-MR charts